

# FILLING WHIPPED CREAM DISPENSER

1



FILL CLEAN **COLD** CANISTER WITH 1 LITRE OF WHIPPING CREAM

2



ADD 4 TEASPOONS OF ICING SUGAR

3



SCREW CAP ON TO CANISTER AND SHAKE WELL

4



PLACE A CO2 CHARGE INTO CANISTER TOP TO PRESSURIZE, SHAKE, THEN REMOVE CHARGE

5



PLACE A SECOND CO2 CHARGE INTO CANISTER. LEAVE IN PLACE

6



SHAKE CANISTER, THEN SLOWLY DISPENSE WHIPPED CREAM UNTIL IT COMES OUT AT THE CORRECT CONSISTENCY

•KEEP CANISTER REFRIGERATED WHEN NOT IN USE